

Recall Date: March 31, 2016

Recall Number: 16-134

Gamewell-FCI Recalls Fire Alarm Panels Due to Failure to Alert of a Fire, Smoke or CO

<http://www.cpsc.gov/en/Recalls/2016/Gamewell-FCI-Recalls-Fire-Alarm-Panels/>

Recall Summary

Name of Product: Gamewell-FCI fire alarm panels (ILI-MB-E3 and ILI-S-E3)

Hazard: When configured in a certain way, the panels can become non-responsive and connected detectors in the area can fail to detect and respond to an alarm.

Remedy: Repair

Consumers should immediately contact the distributor to obtain the free repair, a firmware upgrade. Consumer Contact: Gamewell-FCI at 800-274-4324 from 7 a.m. to 7 p.m. ET Monday through Friday or online at www.gamewell-fci.com and click on "Safety Recall" for more information.

Recall Details

Photos Available At <http://www.cpsc.gov/en/Recalls/2016/Gamewell-FCI-Recalls-Fire-Alarm-Panels/>

Units: About 1,000

Description: This recall is for the ILI-MB-E3 and ILI-S-E3 Gamewell-FCI fire alarm panels in commercial buildings. This issue is limited to a specific configuration of Signaling Line Circuit (SLC) devices. To occur, the SLC must include at least two of the following detectors in any combination: Acclimate, 4-Warn, Photo/CO and iFAAST. The issue would occur only if the detectors are addressed within the same FlashScan polling group. Detectors installed in a different combination are not affected.

Incidents/Injuries: No incidents or injuries have been reported.

Sold at: Authorized distributors from May 2015 through August 2015 for about \$800.

Importer/Distributor: Gamewell-FCI of Northford, Conn.

Manufactured in: U.S.

